



$M \times L$	a	n	t
M 4 x 6	3.2	0.6	1.2
M 4 x 8	3.2	0.6	1.2
M 4 x 10	3.2	0.6	1.2
M 4 x 12	3.2	0.6	1.2
M 4 x 16	3.2	0.6	1.2
M 5 x 5	3.2	0.6	1.5
M 5 x 8	3.2	0.6	1.5
M 5 x 12	3.2	0.6	1.5
M 6 x 5	3.8	0.9	1.8
M 6 x 8	3.8	0.9	1.8
M 6 x 10	3.8	0.9	1.8
M 6 x 12	3.8	0.9	1.8
M 6 x 16	3.8	0.9	1.8
M 6 x 20	3.8	0.9	1.8
M 8 x 10	5.2	1.2	2.7
M 8 x 16	5.2	1.2	2.7
M 8 x 20	5.2	1.2	2.7
M 8 x 30	5.2	1.2	2.7