



$\varnothing D$	s	H	L	M
15.0	1.0	1.5	20.0	M6
16.0	1.0	1.5	20.0	M6
16.0	1.5	1.5	20.0	M6
18.0	1.0	1.5	20.0	M6
18.0	1.5	1.5	20.0	M6
20.0	1.0	1.5	20.0	M6
20.0	1.5	1.5	20.0	M6
22.0	1.0	1.5	20.0	M6
22.0	1.5	1.5	20.0	M6
23.0	1.0	1.5	20.0	M6
24.0	1.0	1.5	20.0	M6
24.0	1.5	1.5	20.0	M6
25.0	1.0	1.5	26.0	M6
25.0	1.5	1.5	26.0	M6
25.0	2.0	1.5	26.0	M6
26.0	1.0	1.5	26.0	M6
26.0	1.5	1.5	26.0	M6
26.0	2.0	1.5	26.0	M6
26.0	2.5	1.5	26.0	M6
27.0	1.0	1.5	26.0	M6
27.0	1.5	1.5	26.0	M6
27.0	2.0	1.5	26.0	M6
27.0	2.5	1.5	26.0	M6
28.0	1.0	1.5	26.0	M6
28.0	1.5	1.5	26.0	M6
28.0	2.0	1.5	26.0	M6
28.0	2.5	1.5	26.0	M6
30.0	1.0	1.5	26.0	M6
30.0	1.5	1.5	26.0	M6
30.0	2.0	1.5	26.0	M6
32.0	1.0	1.5	26.0	M6
32.0	1.5	1.5	26.0	M6
32.0	2.0	1.5	26.0	M6
32.0	2.5	1.5	26.0	M6
38.0	1.0	1.5	29.0	M8
38.0	1.5	1.5	29.0	M8
38.0	2.0	1.5	29.0	M8
40.0	1.5	1.5	29.0	M8
40.0	2.0	1.5	29.0	M8
40.0	2.5	1.5	29.0	M8
40.0	3.0	1.5	29.0	M8

Poznámka: Spojky jsou zajištěny v trubce na principu hmoždinky.