



Návleky kruhové průmyslové Typ: 062d-110-dxh
Materiál: PE, Barva: červená




$\varnothing d$	h	$\varnothing d$	h
8.9	8.0	53.5	12.3
19.0	13.0	57.0	12.5
22.1	11.0	59.5	12.5
25.5	13.1	63.0	12.6
28.5	13.3	66.4	11.0
31.7	12.8	69.8	12.1
34.7	12.5	72.5	12.6
38.0	12.2	75.5	12.3
41.2	12.8	79.4	12.7
44.5	12.4	82.0	12.3
47.0	12.4	85.0	12.2
50.3	11.7		

Návleky kruhové průmyslové Typ: 062e-110-dxh
Materiál: PE, Barva: bílá




$\varnothing d$	h
25.0	37.0
31.0	39.0
43.0	43.0
57.0	44.0
70.0	47.0
81.5	54.0

Návleky kruhové průmyslové Typ: 062-388-dxh
Materiál: PE, Barva: přírodní




$\varnothing d$	h	$\varnothing d$	h
4.0	22.0	20.0	22.0
5.0	22.0	22.0	28.0
5.8	7.0	23.0	28.0
6.0	22.0	24.0	30.0
6.3	22.0	25.0	36.0
7.0	22.0	28.5	21.0
8.0	34.0	29.5	51.0
9.0	22.0	51.5	10.0
10.0	34.0	51.5	59.0
11.0	22.0	51.5	100.0
12.0	34.0	58.0	35.0
13.0	22.0	62.0	8.0
14.0	22.0	78.0	25.0
15.0	22.0	80.0	25.0
16.0	22.0	89.0	48.0
16.0	36.0	91.0	18.0
17.2	20.0	92.0	18.0
18.0	22.0	99.0	13.0
19.0	22.0	100.0	40.0

Návluky kruhové průmyslové Typ: 062-034-dxh
Materiál: PE, Barva: přírodní



$\varnothing d$	h	$\varnothing d$	h
5.7	12.0	29.3	18.0
7.8	14.3	33.4	22.5
9.8	11.0	33.4	45.0
10.2	8.0	34.8	25.0
10.5	8.0	35.7	14.0
11.5	12.0	37.5	20.0
12.7	13.5	41.9	28.0
12.7	18.0	47.8	29.5
13.5	13.5	51.6	16.0
15.7	15.0	52.5	30.0
15.7	22.8	56.7	19.0
15.9	14.0	59.7	30.0
17.7	15.0	69.8	25.0
19.7	14.0	75.5	35.0
20.6	15.0	75.8	18.0
23.5	18.5	79.8	25.0
25.4	17.5	88.4	36.0
26.2	18.5	108.8	22.4

Návluky kruhové průmyslové Typ: 062-068-dxh
Materiál: PE, Barva: přírodní



$\varnothing d$	h	$\varnothing d$	h	$\varnothing d$	h	$\varnothing d$	h
4.0	22.0	24.8	17.0	75.0	38.0	146.0	40.0
5.0	18.0	25.4	20.0	77.0	35.0	148.0	35.0
6.0	18.0	26.0	20.0	78.0	26.0	156.0	40.0
6.4	18.0	28.5	23.5	80.0	29.5	159.0-160.0	49.5
7.0	18.0	29.0	25.0	82.0	30.0	165.0	40.0
8.0	19.0	30.0	27.5	83.0	30.0	170.0	45.0
9.6	18.0	31.8	20.0	85.0	30.0	176.0	40.0
10.0	18.0	35.0	27.0	90.0	30.0	177.8	40.0
11.0	15.0	36.5	20.0	92.4	25.0	180.0	40.0
11.5	19.5	38.0	20.0	95.0	37.5	185.0	40.0
12.0	19.5	40.0	27.0	98.0	37.5	190.0	40.0
12.7	19.0	41.3	19.5	100.0	31.0	193.7	42.0
13.0	18.0	44.5	20.0	103.0	40.0	200.0	50.0
13.7	18.0	45.4	20.0	106.0	40.0	210.0	40.0
14.0	20.0	47.5	25.0	108.0	35.0	225.0	39.0
15.0	18.0	51.0	27.5	110.0	38.0	232.0	40.0
15.5	15.0	52.0	33.0	116.3	40.0	242.0	50.0
16.0	20.0	52.8	23.0	117.5	40.0	245.0	49.0
17.2	20.0	54.0	27.5	120.0	39.0	250.0	47.0
18.0	18.0	55.0	29.0	121.0	38.0	267.0	43.0
18.5	18.0	57.0	26.5	125.0	35.0	280.0	61.0
19.0	18.0	63.5	27.0	130.0	40.0	315.0	50.0
20.0	20.0	65.0	30.0	133.0	40.0	366.0	54.0
22.0	20.0	67.0	30.0	136.0	40.0	400.0	65.0
23.2	17.0	70.0	34.5	138.0	32.5	419.0	60.0
24.0	17.0	73.0	20.0	141.3	34.5	450.0	65.0